

Project: Commercial Top Landing Settlement **Date:** March, 2019

Location: Middlesex County College, Middlesex NJ

Problem: Settled slab on the top landing of a main entrance step, creating a major tripping hazard

To raise the slab, the college's facilities management first chose a local, multi-service company. Company representatives claimed they could raise the slab through a $\frac{5}{8}$ inch hole pumping in a newer, superior product (poly foam) over concrete mudjacking.

After two different attempts, including one with an onsite consultation with the company's poly-leveling manager, the slab was not lifted. Both attempts left unsightly holes closer to 3" inches in diameter. The contractor's work order was cancelled.

Solution: Hire a mudjacking specialist to fix the job

Unlike the prior contractor, Concrete Chiropractor specializes in concrete raising. Our technicians raised and stabilized the slab back to its original height, therefore removing the tripping hazard. Our process pumped a lab-tested, natural product into smaller holes than left behind by the prior contractor, gradually lifting the slab.

End result: Satisfied client

A representative from the college's facilities management happily stated, "You are true experts in concrete raising, and you will be our go-to contractor from this point forward."

Project Summary

Concrete Chiropractor was able to save the project where others had failed. While competitors heavily market a variety of products and services, we only specialize in concrete repair. Our time proven system and product is backed up with a solid warranty. Our reputation speaks for itself, demonstrated repeatedly by our satisfied clientele and their referrals.

